

F) 400/220k.V ICT.

Out of the above except the faulty line of 220k.V singaji-Chegaon-2 all other elements were **restored at 19.55 hrs**

and the system is presently normal.

The detailed report is awaited from M/S MPSEB and on receipt of the flash report , the same will be forwarded to you for your kind info and n.a please.

(S/IWRLDC)

S/I MPSEB: with the request to send the detailed report at the earliest please.

—

पा.प्र. सं.(SCM)

नियंत्रण कक्ष (Control Room)

पश्चिम क्षेत्रीय भार प्रेषण केंद्र, मुंबई

(Western Regional Load Despatch Centre, Mumbai)

संपर्क (Contact) - 022-28203885, 28397634

पन. काम(PUNCOM) - 500-112,113,114,115

फैक्स (FAX) - 022-28202630,93

पन. काम फैक्स(PUNCOM FAX) -500101

Information contained and transmitted by this email is confidential and proprietary to The Power System Operation Corporation Ltd. and is included for use only by the addressee. If you are not the intended recipient, you are notified that any dissemination or copying of this email or contents therein is strictly prohibited. If this message is not intended for you, then you are requested to delete this email immediately and notify the originator.